

**Marker: 01-02**

**Names:** Nancy Adeline HUTCHENS CR

**Planned Treatment:**

epoxy three breaks, infill with mortar, and attach marble backer with mortar

**Actual Treatment:** 8/10/2022

epoxied three breaks, infilled with mortar, and attached marble backer with mortar

01-02-PXL\_20220804\_204904152



01-02-PXL\_20220810\_234411409



01-02-PXL\_20220828\_232157820



01-02-PXL\_20220828\_232206769



**Marker: 01-19**

**Names:** Belle WARNER

**Planned Treatment:**

epoxy two breaks

**Actual Treatment:** 8/10/2022

epoxied two breaks

01-19-PXL\_20220804\_205014809



01-19-PXL\_20220822\_181940872



01-19-PXL\_20220822\_182316833



01-19-PXL\_20220828\_230520958



**Marker: 02-06**

**Names:** William MOORE

**Planned Treatment:**

epoxy two breaks, infill with mortar, and attach marble backer with mortar

**Actual Treatment:** 8/10/2022

epoxied two breaks, infilled with mortar, and attached marble backer with mortar

02-06-PXL\_20220804\_205119025



02-06-PXL\_20220822\_175907277



02-06-PXL\_20220828\_231723737



02-06-PXL\_20220828\_231742575



**Marker: 05-03**

**Names:** Mary Alice HILL

**Planned Treatment:**

epoxy two breaks and infill with lithomex

**Actual Treatment:** 8/10/2022

epoxied two breaks and infilled with lithomex

05-03-PXL\_20220810\_214734067



05-03-PXL\_20220810\_231847933



05-03-PXL\_20220810\_232426464



05-03-PXL\_20220828\_230240501



**Marker: 19-15**

**Names:** Sarah BROWN

**Planned Treatment:**

level on gravel, currently at 9 degrees

**Actual Treatment:** 8/10/2022

leveled on gravel

19-15-PXL\_20220810\_210705172



19-15-PXL\_20220810\_211851349



19-15-PXL\_20220810\_213141300



19-15-PXL\_20220810\_214101706



***Total Number of Stones Treated: 5***

***GLOSSARY:***

*"Cleaning" refers to a light scrubbing with water and a tampico brush and an application of D/2.*

*"Epoxy" refers to Akepox 2010.*

*"Gravel" refers to 3/4"-minus crushed gravel.*

*"Lithomex" refers to a natural hydraulic lime mortar patching compound.*

*"Mortar" refers to natural hydraulic lime mortar (NHL 3.5).*